

1995 GET 17 PILEST WENDOVER

DEPT OF INTERIOR BUR, OF LAND MOMT

Mr. Douglas M. Koza
Deputy State Director
Bureau of Land Management
324 South State, Suite 301
Salt Lake City, Utan 84111-2303

October 16, 1995

SUBJECT: Minor amendment to 1975 Mine Plan

Dear Mr. Koza:

Pond system five has been in production since about 1978. It was designed and constructed on a twenty year life. Since this was the first pond to be constructed on a twenty year life, the actual life was not known. Reilly Wendover has in the last few years performed maintenance on the perimeter dike. At the close of this evaporation season the perimeter dike was evaluated. The north end of the dike is in very bad condition and requires

The bern (A) see map) is to harrow for a dragline and the barrow is to wide for a dragline to set (B) see map) and reach the dike. Therefore it has been proposed to go outside the borrow approximately 250 feat (see map) and construct a new cut-off dike. The new dike would be 14,300 feet long and 15 feet high. It would be of the same design and construction as the original dike in pond system five.

I cannot over emphasize how critical the condition of the existing dike is. I would appreciate your rapid response to this Minor amendment to the mine plan. Thank you.

Sincerery,


Afem D. Washworth

Glénn D. Wadsworth Flant Manager

cc: Stan Perks — BLM - R所述於在此時間的學家的 Clarence Prentice — Indianapolis


Enclosure - Map

DIKE MAINTENANCE POND V



2ond

lide





United States Department of the Interior

3UREAU OF LAND MANAGEMENT Salt Lake District Office

2370 South 2300 West Sait Lake City, Urah 84119

IN REPLY REFER TO:

8111 Projects (UT-024)

OCT 26 1995

Mr. Max J. Evans Utah State Historic Preservation Officer 300 South Rio Grande SLC, Ut 84101

Dear Mr. Evans:

In order to comply with Section 106 of the National Historic Preservation Act of 1966, the Salt Lake District of the Bureau of Land Management requests your views on our efforts to identify historic properties for the following project (as specified in 36CFR 800.4 (a) (ii):

POND SYSTEM FIVE DIKE

The above project is located on the Salt Flat, south of the National Register Listed site (42TO706), the Bonneville International Raceway (please see project and location maps).

The project is located on the salt flat and the possibility for cultural resources is low. The area has already been impacted by twenty years of mining and additional surface disturbance will not affect the qualities that make (42TO706) a significant historic property.

Therefore, we seek your concurrence that no Cultural Resources Inventory is necessary.

For further information please contact Melvin G. Brewster of this office at (801) 977-4358. If we do not hear from your office within 15 days, we will assume your concurrence and proceed.

Margaret Wyatt Acting for DEANE H. ZELLER

DISTRICT MANAGER